



P.O. Box 226 • Seneca, KS 66538 • 785/336-3760  
FAX 785/336-2751 • <http://www.krwa.net>

June 28, 2010

Brian Howe  
Jackson Heights, USD 335  
12692 266<sup>th</sup> Road  
Holton, KS 66436

Dear Brian,

As requested, I responded to your request concerning storm water entering the sanitary sewer.

You identified the problem being on the east side of the lagoon system where a waterway had been changed. It appeared that water had been flowing directly into the lagoons from the east. I agree that this is the largest contributor to storm water entering the lagoons. The flow in the waterway needs to be directed away from the lagoons.

We identified five problems in the smoke testing that we conducted. These include two manholes and three cleanouts. The cleanouts are in a waterway just south of the lagoon system. During heavy rain events, there could also have storm water entering these cleanouts. The two manholes are located: 1) just to east of the north drive to parking lot of the football field area; and, 2) the other is in driveway southeast of the superintendent's office.

Since this was such a small area and very little material was used there will be no fee for the smoke testing.

Please call if you have any questions. KRWA appreciates the opportunity to provide assistance to your system.

Sincerely,

Charlie Schwindamann  
Wastewater Tech

CS: ejr  
C: Paul Becker, USD Superintendent  
Helen Holm, KDHE, Lawrence